

Sale Name: August 8, 2025 - Truck, Trailer and Equipment Auction

LOT 87916 - 2019 INTERNATIONAL LT625 T/A SLEEPER



VIN 3HSDZAPR3KN064536

Year 2019

Make INTERNATIONAL

Model LT625

Detailed Category T/A SLEEPER

Exterior Color Black

Odometer Reads 622010

Engine Hours Read 16987

Engine Make Cummins

Engine Model X15

Engine Size 15.0 L

Engine Cylinders 6

Engine HP 450 SA

Engine Brake Yes

Transmission Make Eaton Fuller

Transmission Model Endurant

Transmission Speed 12

Transmission Type Automatic

GVW 52350

Front Axle Weight (LBS) 12350

Rear Axle Weight (LBS) 40000

Locking Differential Single

Number of Axles Tandem

Suspension Type Air

Wheel Base (inches) 232"

Rear Brakes Air Disc

Wet Line No

APU Yes

Sleeper Size (Inches) 70"

Sleeper Double Bunk

Tire Size 275/80R22.5

Wheels Front Aluminum

Wheel Rear Aluminum

Fifth Wheel Air Sliding

Fuel Type Diesel

Number of Fuel Tanks Dual Fuel Tank

Gallon Capacity (total) 200

Exhaust Single Stack

Power Steering Yes

Power Windows Yes

Cruise Control Yes

Air Conditioning Yes

Heated Mirrors Yes

Lane Mitigation Yes

Notes Go Green APU, left front vibrates, Check engine lights, DPF light on, fuel line to #6 cylinder is blocked off

Stock # 87916

Description

2019 INTERNATIONAL LT625 T/A SLEEPER **VIN:** 3HSDZAPR3KN064536 **OD Reads:** 622010 **Engine Hours Read:** 16987 **Eng:** Cummins X15 **Liters:** 15.0 L **Cyl:** 6 **HP:** 450 SA **Jake:** Yes **Trans:** Eaton Fuller Endurant **SP:** 12 Automatic **GVW:** 52350 **Front Axle (LBS):** 12350 **Rear Axle (LBS):** 40000 **Locking Diff:** Single **Axles:** Tandem **Susp:** Air **WB:** 232" **Rear Brakes:** Air Disc **Wetline:** No **APU:** Yes **Sleeper Size:** 70" Double Bunk **Tire Size:** 275/80R22.5 **Front Wheels:** Aluminum **Rear Wheels:** Aluminum **Fifth Wheel:** Air Sliding **Fuel:** Diesel Dual Fuel Tank **Gal Cap:** 200 **Exh:** Single Stack **PS:** Yes **PW:** Yes **Cruise:** Yes **AC:** Yes **Heated Mirrors:** Yes **Lane Mitigation:** Yes **Ext Color:** Black **Notes:** Go Green APU, left front vibrates, Check engine lights, DPF light on, fuel line to #6 cylinder is blocked off **Stock #** 87916

Quantity: 1



<https://www.hessauctioneers.com/>